U. S. COAST & GEODETIC SURVEY LIBRARY AND ARCHIVES

MAR 14 1934

Acc. No. _

Form 504 Ed. June, 1928

DEPARTMENT OF COMMERCE

U. S. COAST AND GEODETIC SURVEY

R.S.Patton Director

State: California.

DESCRIPTIVE REPORT

Tagragaopacex |

Hydrographic

Sheet No. S.D. 51.

LOCALITY

San Diego Bay.

San Diego Bay Entrance.

1934...

CHIFF OF BARTY

Robert W. Knox

U. S. COAST & GEODETIC SURVEY LIBRARY AND ARCHIVES

MAR 13 1934

Acc. No.

REPORT

to accompany

Sheet No. S. D. 51.

Scale 1:5,000

San Diego Bay Entrance,

California.

Date of Instructions: Telegraphic Instructions dated Jan. 17, 1934.

Survey Methods: A Navy motor sailer and the motor launch of the chartered launch "JOANNE" were used to do the sounding on this sheet. Standard Coast Survey methods were used.

Discrepancies: There are two discrepancies in depths noted on the sheet. The first is a difference of 5 feet in the soundings in the vicinity of Lat. 32°-42' plus 281 meters, Long 11%°-13' plus 1193 meters. The other is a discrepancy of 3 feet in Lat. 32°-42' plus 40 meters. More Long. 11%°-13' plus 1305 meters. These differences occur on the first day of sounding and it is thought that they are due to the inexperience of a new boat crew.

Control: All centrol is from triangulation executed in 1933.

Signal Ball is a hydrographic location, located by sextant fixes on the object.

PLotting: Smooth plotting was done in the Long Beach office by civilian personnel under the supervision of the Chief of Party.

The sheet was review after completion by the undersigned.

John C. Mathisson,

Jr. H. & G. 🖫

STATISTICS

San Diego Bay Entrance

Scale 1:5,000

Day	Date	No. Sdgs.	No. Pos.	Stat. Mi.	Boat used.
a	Jan. 22	159	57	1.5	M.S.
ъ	" 23	-	6		M.S.
c	Feb. 5	336	93	4.9	M.L.
	Totals	495	156	6.4	

DEPARTMENT OF COMMERCE U. S. COAST AND GEODETIC SURVEY

HYDROGRAPHIC TITLE SHEET

U. S. COAST & GEODETIC SURVEY
LIDRARY AND ARCHIVES

MAR 13 1934

Z

Acc. No.

70:

The Hydrographic Sheet should be accompanied by this form, filled in as completely as possible, when the sheet is forwarded to the Office.

Field No. S.D. 51

REGISTER NO. 5404

State CALIFORNIA	
General locality Saw misco that FO NIA	
Locality SAN DIEGO BAY ENTRANCE Targe.	
Scale 1: 5,000 Date of survey Jan - Feb. 19 3	4
Vessel U.S. Navy moter sailer and hired motor launch "JOA	
Chief of Party Robert W. Knox	
Surveyed by R. J. Sipe	nivelidă
Protracted by D. L. Ackland	
Soundings penciled by D. L. Ackland	
Soundings in THINESE feet	
Plane of reference M.L.L.W. on staff at La Playa, Cal	if.
Subdivision of wire dragged areas by	
Inked by	
Verified by	
Instructions dated Jan. 17 (telegraphic) 19 34	
Remarks:	 *: ::-e•

Division of Hydrography and Topography:

March 14, 1934

Division of Charts:

Tide Reducers are approved in

1 volumes of sounding records for

HYDROGPAPHIC SHEET 5404

Locality San Diego Bay Entrance, Calif.

Chief of Party: Robert W. Knox in 1934
Plane of reference is mean lower low water, reading
1.7 ft. on tide staff at La Playa
9.5 ft. below B. M. 9

Height of mean higher high water above plane of reference is 5.7 feet.

Condition of records satisfactory except as noted below:

Acting Chief, Division of Tides and Currents

Deld Record Section mas 16, 1934 Report on A 5404 Chief of Party: Role W. Knop Surveyed by: R.J. Supe. Protracted by: D. D. ackeland. complete, complete The protesting in general was good.

The soundings in some instances were correctly plotted to to time and amount was not made for turns at end of lines. The day letter are blue in the Sounding wood & red on the smooth sheet This was corrected. The field drofting in general was good.

SECTION OF FIELD RECORDS Review of Hydrographic Sheet No. 5404

San Diego Entrance, San Diego Bay, California. Surveyed Jan. - Feb. 1934.

Instructions telegraphic dated Jan. 17, 1934 (Knox).

Chief of Party - R. W. Knox.
Surveyed by - R. J. Sipe.
Protracted and soundings plotted by - D. L. Ackland.
Verified and inked by - I. M. Zeskind.

- 1. Records conform to the requirements of the Hydrographic Manual.
- 2. The plan and extent of development conform to the regulations and satisfy the specific instructions.
- 3. Soundings are consistent and depth at crossings of lines in good agreement, generally less than 1 foot of difference.
- 4. Depth curves. The 30 foot curve is well developed and sections of the 18 foot curve are shown.
- 5. Junctions. This is a special investigation and no contemporary surveys adjoin it. H. 4268 (1923) is the basic survey for this area.
- 6. Comparison. B. P. 21379 shows the eastern edge of the channel as widened by dredging, August 1927. The present survey shows that the 50 foot curve has moved westward about 65 meters in the vicinity of the lighted buoy 8B. The position of the buoy has been changed since the survey, the former location is shown on the sheet.
- B. P. 27230 is an advance copy of this survey (H. 5404) apparently traced from the boat sheet. There are a number of errors in tracing depth values as well as quite a number of soundings that differ by only 1 or 2 feet.

Chart 5107 shows the conditions that existed immediately after the dredging in 1927.

- 7. Field drafting in general was good, but more care should have been exercised in the penciling of the soundings both as to spacing and values.
- 8. Recommendation. This sheet (H. 5404) should supersede all previous information for charting the area represented by it.

Resurveys at stated intervals to determine the extent and progress of the shealing in this vicinity are desirable.

9. Reviewed by - R. J. Christman - March 19, 1934.

L. O. Colbert.

Examined and approved;

Chief, Section of Field Records.

Chief Diwigian of Chante

Chief, Section of Field Work.

Chief, Division of H. & T.

25 Ju 24, 1936 Lap

.

.

والمدعومة أأسا